



High-Speed Logger for SPS USB Power Sensor

User Guide

© Aeroflex Ltd. 2014
Longacres House
Six Hills Way
Stevenage SG1 2AN
UK

*No part of this document may be reproduced or transmitted in any form
or by any means, electronic or mechanical, including photocopying,
or recorded by any information storage or retrieval system,
without permission in writing by Aeroflex Ltd.
(hereafter referred to throughout the document as 'Aeroflex').*

Document no. 47090/306

Issue 1

14 August 2014

About this document

This document explains how to use the High Speed Logger application to record measurement results and metadata from the SPS USB Power Sensor.

Intended audience

Persons engaged in the design and manufacture of RF and microwave sub-systems and modules, or the installation and maintenance of those systems.

Familiarity with the terms used in RF and microwave measurements is assumed.

Associated publications

- SPS USB Power Sensor Quick Start Guide
(PDF version 47090/177, printed version 47000/177)
- SPS USB Power Sensor Operating Manual
(PDF version 47090/178, printed version 47000/178)
- SPS-8 CW and Pulse USB Power Sensor data sheet

Contents

About this document	2
Intended audience	2
Associated publications	2
Introduction	4
Using the HSL application	5
Data storage tab	7
Measurement tab	8
Meas Start and Meas Stop tabs	9
Start criteria	10
Delay criteria	10
Stop criteria	11
Meas Spacing tab	11
Measure as fast as possible	11
Delay between points	12
Usage issues	13
Examples of use	14
Simplest measurement: Start/Stop buttons	14
Threshold measurement with delay and time expiration	15
Start and stop using time of day and measurement spacing	15

Introduction

This document applies to the High Speed Logger (HSL) application. This application is intended to be useful both as an end application and to demonstrate the capabilities of the SPS power sensors. We provide the application and the source code. You are free to modify the source code as you see fit for use with SPS power sensors. The application and source code are 'as is': as such, no warranty or guarantee of any type is implied.

Before installing this application, ensure that you have installed the most recent power meter or pulse profiling applications. These installations install the drivers onto your operating system. Then, using normal procedures, install this application (run the setup). The source code is available in a separate directory. The project is a C#, VS2005 project.

Using the HSL application

After you complete the installation, ensure that you can run the power meter application. If so, you are ready to run this HSL application. Assuming you have a single power sensor attached, when you start the application you see a window similar to the one shown below:




Fig. 1 Logger startup window

By clicking **Yes**, the sensor is initialized and you are ready to start making measurements. The window you see next is:





Fig. 2 Device initialize window

Note that the selected sensor is highlighted. If there are multiple sensors, you need to select a sensor and click **Initialize Sensor**. You may initialize several sensors. The selected and initialized sensor is the sensor used to make the measurements.

Data storage tab

The device initialize window shown in Fig. 2 has five tabs. The first tab is Data Storage:



The screenshot shows a window titled "Data Storage" with five tabs: "Data Storage", "Measurement", "Meas Start", "Meas Stop", and "Meas Spacing". The "Data Storage" tab is selected. The window contains the following fields and options:

- Path:** A text box containing "c:\", followed by a "Browse..." button.
- File Name:** A text box containing "test".
- Final File Name:** An empty text box.
- Append date & time stamp to file name
- View Data upon Completion
- File Delimiter:** A group box containing two radio buttons:
 - Comma Separated Data
 - Tab Separated Data

Fig. 3 Data Storage window

Data Storage specifies:

- Where files are stored — type in the directory directly or click **Browse...** to search for a directory.
- Date and time stamp modifications to the file name — type in the file name. If you check 'Append date & time stamp to file name', the date and time is appended to the specified file name and is modified each time a new set of data is taken. This allows you to take several sets of data without having to specify a new name. It also groups the files together in the file browser.
- How the data is displayed. Checking 'View Data upon Completion' causes the data to be displayed in Notepad (by default) when the measurements are complete.
- The format of the files (tab- or comma-delimited). Tab-delimited works well with spreadsheet applications like Microsoft Excel.

Measurement tab

The second tab is Measurement:




Fig. 4 Measurement window

Use the Measurement tab to select the type of measurement, the units and the frequency. You must set the frequency to get accurate measurements. If CW is selected, only the average or CW power is recorded. If 'Peak, pulse, average power, duty cycle & crest factor' is selected, all of these parameters are recorded. The following text is from CW measurements. The data is tab-delimited.

```

index  time (msec)  CW (dBm)
000001 000026.849  -034.387
000002 000027.130  -034.389
:
:
000019 000031.379  -034.387
000020 000031.625  -034.386
000021 000031.878  -034.393
000022 000032.132  -034.399
000023 000032.383  -034.386
    
```

This data is from peak measurements:

```

index  time (msec)  Pk (dBm)  P1s (dBm)  CW (dBm)  CrF (dB)  DC (%)
000001 000037.097  -034.284  -034.387  -034.387  000.103 100.000
000002 000037.967  -034.274  -034.390  -034.390  000.115 100.000
000003 000038.212  -034.317  -034.392  -034.392  000.076 100.000
    
```

The first column in both instances is the index of the measurement. The second column is the relative elapsed time. The remaining data is measurement results.

Meas Start and Meas Stop tabs

The next two tabs, Meas Start and Meas Stop, let you specify the starting and stopping criteria:

Fig. 5 Meas Start window

Fig. 6 Meas Stop window

The Meas Start tab is used for starting the measurement process. The Meas Stop tab is used for stopping the measurement process. The measurement process proceeds as follows:

- 1 Satisfy the start criteria
- 2 Execute a delay if requested
- 3 Make the measurements
- 4 Stop when the appropriate criteria are satisfied.

Start criteria

There are four types of start criteria:

- The **Start** button — clicking **Start** begins the measurement process.
- A threshold — clicking **Start** causes the application to monitor the incoming measurements (average power if CW has been selected and peak power if peak has been selected). As soon as the appropriate measurement exceeds the specified threshold the measurement proceeds. The threshold is specified in dBm.
- External TTL trigger (*not currently supported*) — clicking **Start** causes the application to monitor the incoming trigger. When a trigger occurs, the measurement continues. Note that only the first measurement requires a trigger. The trigger timeout is settable. If the timeout occurs before the measurement begins, no measurements are made.
- Time of day — you can set the start time and the stop time (hours (24-hour clock), minutes, seconds). Some situations might cause unintended events.
- The following shows four different arrangements of the start and stop time. Because of the potential file size, some consideration should be taken with regard to measurement spacing.
 - This is the 'normal' case. The specified start time is later than the current time and the stop time is later than the start time. In this example the measurements start at 2:05 p.m. and continue for five minutes until 2:10 p.m.:
 - **Start** button is clicked: 14:00:00 (or 2 p.m.)
 - Start time: 14:05:00 (or 2:05 p.m.)
 - Stop time: 14:10:00 (or 2:10 p.m.)
 - The specified start time is later than the current time and the stop time is earlier than the start time. In this example the measurements start at 2:05 p.m. and continue for 23 hours and 59 minutes until 2:04 p.m. the following day:
 - **Start** button is clicked: 14:00:00 (or 2 p.m.)
 - Start time: 14:05:00 (or 2:05 p.m.)
 - Stop time: 14:04:00 (or 2:04 p.m.)
 - The specified start time is earlier than the current time and the stop time is later than the start time. In the example below, the clock starts and runs almost a full day until it becomes 1:05 p.m. the following day. At this time, it begins measurements. Measurements continue for five minutes and then stop.
 - **Start** button is clicked: 14:00:00 (or 2 p.m.)
 - Start time: 13:05:00 (or 1:05 p.m.)
 - Stop time: 13:10:00 (or 1:10 p.m.)
 - The specified start time is earlier than the current time and the stop time is earlier than the start time. In the example below, the clock starts and runs almost a full day until it becomes 1:05 p.m. the following day. At this time, measurements begin. Measurements then continue for 23 hours and 59 minutes, stopping the day after tomorrow.
 - **Start** button is clicked: 14:00:00 (or 2 p.m.)
 - Start time: 13:05:00 (or 1:05 p.m.)
 - Stop time: 13:04:00 (or 1:04 p.m.)

Delay criteria

Now that the start criteria are satisfied, a delay (milliseconds) can be set. The delay begins immediately after the start criteria have been met and precedes the onset of measurements.

Stop criteria

The final item is the stop criteria. As well as setting the stop time as shown [above](#), there are three additional ways to stop the measurement process:

- 1 Clicking the stop button (always available).
- 2 The measurement process ends when the specified time has expired (milliseconds).
- 3 The measurement process ends when the specified number of measurements has been made.

Meas Spacing tab

The final tab, Meas Spacing, is shown below:




Fig. 7 Meas Spacing window

This tab has two options: 'Measure as fast as possible' and 'Delay between points'.

Measure as fast as possible

This option makes a measurement at the rate of approximately 350 μ sec per point on most computers, although some computers may be faster, some slower. Many factors may affect this rate. Virtually any loading on the computer may slow the rate of measurement. The magnitude of the effect is a function of the power of the computer and the demands of the competing applications. In most cases these effects are modest, but they should not be ignored.

Delay between points

This value (in milliseconds) is negatively impacted by many of the same factors. Again, these effects tend to be modest in most cases and pose little concern. The resolution and accuracy of the computer clock has some effect. Below are samples of data: in the first set, the data is as fast as possible.

002796	000773.664	-034.323	-034.397	-034.397	000.075 100.000
002797	000773.922	-034.304	-034.393	-034.393	000.089 100.000
002798	000774.163	-034.313	-034.391	-034.391	000.078 100.000
002799	000774.415	-034.313	-034.390	-034.390	000.077 100.000
002800	000774.787	-034.284	-034.397	-034.397	000.113 100.000
002801	000775.040	-034.313	-034.394	-034.394	000.082 100.000
002802	000775.287	-034.330	-034.397	-034.397	000.067 100.000
002803	000775.540	-034.323	-034.395	-034.395	000.073 100.000
002804	000775.792	-034.296	-034.396	-034.396	000.099 100.000
002805	000777.776	-034.304	-034.402	-034.402	000.097 100.000
002806	000778.041	-034.291	-034.388	-034.388	000.098 100.000
002807	000778.291	-034.300	-034.392	-034.392	000.092 100.000
002808	000778.538	-034.299	-034.394	-034.394	000.095 100.000
002809	000778.793	-034.300	-034.387	-034.387	000.087 100.000

A quick look at all the data results in the following:

- Maximum time between points = ~1.984 ms
- Minimum time between points = ~0.137 ms
- Average time between points = ~0.263 ms

In the second set, the data is taken with a 20 ms delay between points:

000131	002702.506	-034.317	-034.382	-034.382	000.065 100.000
000132	002723.005	-034.304	-034.385	-034.385	000.081 100.000
000133	002743.649	-034.315	-034.382	-034.382	000.067 100.000
000134	002764.148	-034.298	-034.387	-034.387	000.089 100.000
000135	002784.649	-034.297	-034.379	-034.379	000.082 100.000
000136	002805.151	-034.293	-034.384	-034.384	000.091 100.000
000137	002825.656	-034.304	-034.380	-034.380	000.076 100.000
000138	002846.177	-034.311	-034.385	-034.385	000.074 100.000
000139	002866.664	-034.283	-034.378	-034.378	000.095 100.000
000140	002887.165	-034.264	-034.376	-034.376	000.112 100.000
000141	002907.667	-034.302	-034.385	-034.385	000.083 100.000
000142	002928.166	-034.298	-034.385	-034.385	000.087 100.000
000143	002948.663	-034.306	-034.383	-034.383	000.077 100.000
000144	002969.174	-034.293	-034.381	-034.381	000.088 100.000
000145	002989.663	-034.280	-034.378	-034.378	000.098 100.000
000146	003010.299	-034.297	-034.380	-034.380	000.083 100.000
000147	003030.789	-034.296	-034.387	-034.387	000.091 100.000

A simple analysis of this data shows the following:

- Maximum time between points = 20.644 ms
- Minimum time between points = 20.003 ms
- Average time between points = 20.505 ms

While there is some variation in timing, it is better than anticipated. What is known is that the measured time (using the computer's clock) is generally quite accurate over short periods (less than several seconds).

Usage issues

If unconstrained, this application consumes memory and disk space very rapidly. As a result, memory faults can occur. Since this application has a dual purpose, error checking has been minimized: in fact, only the absolute minimum error trapping is included. Errors typically occur in one area but for two different but related reasons. The first reason is that you cannot view the text file. This is probably because the text file written during measurements is too large for the application trying to display the file (for example, Notepad). The second reason that errors may occur is because of insufficient memory (RAM). Each measured point requires approximately 54 bytes. If there is insufficient memory and no attempt is made to reduce memory usage, it is possible to simply run out of RAM.

The primary means of minimizing the usage of memory is to use the [Meas Spacing tab](#). Measuring as fast as possible consumes about 150–220 bytes per millisecond, or about 150–220 kB/s. This translates to about 13 MB per minute or 790 MB per hour. However, reducing the duration of measurements down to 10 ms consumes 20 MB of RAM per hour.

The 20 MB of RAM per hour would be tolerable for most systems. Even a 24-hour logging event translates to less than 500 MB.

However, text file usage is more problematic because text is less efficient. You can assume about 100 kB/s for CW and 250 kB/s for pulse (based on three or four measurements per millisecond). Files can become very large very quickly. If you are aware that viewing the files might be a problem, the easiest way to mitigate the issue is to turn off viewing of data.

Spreadsheets also have limitations (number of rows and columns). In each case, you need to be aware of these limitations and take appropriate action.

Examples of use

The following outlines how to make a few simple measurements using the HSL. This assumes that a single sensor is connected and that you have installed the applications.

Simplest measurement: Start/Stop buttons

- 1 Open or start the HSL (High Speed Logger).
- 2 Click **Yes** to initialize the sensor.
- 3 Click **OK** when the 'Device initialized' message is shown.
- 4 Click the first tab ([Data Storage](#)) if it is not shown
- 5 Click the **Browse** button and select Desktop (your desktop) — click **OK**.
- 6 Enter 'TestFile' into the File Name textbox.
- 7 Ensure 'Append date & time stamp to file name' is checked.
- 8 Ensure 'View Data upon Completion' is checked.
- 9 Select the 'Tab Separated Data' radio button.
- 10 Click the [Measurement](#) tab.
- 11 Select the 'CW (or average)' radio button.
- 12 Set Units = dBm.
- 13 Set Freq = 1.000 GHz.
- 14 Click the [Meas Start](#) tab.
- 15 Select the '...start button is clicked' radio button.
- 16 Click the [Meas Stop](#) tab.
- 17 Select the '...stop button is clicked' radio button.
- 18 Click the [Meas Spacing](#) tab
- 19 Select the 'Measure as fast as possible' radio button.
- 20 Now click **Start**. Wait one or two seconds and click **Stop**.
- 21 Upon clicking **Stop** a Notepad or text file should appear, with data similar to that shown below. Depending on the time between clicking Start and Stop, you may have several thousand lines. If you used tab-delimited text you should be able to copy and paste portions of this file directly into Excel. Finally, if you used 'Desktop' as your path you should see the icon for the file on your desktop. If you examine the name of the file you should see the data and time appended to the file.

index	time (msec)	CW (dBm)
000001	000023.444	-034.388
000002	000023.702	-034.384
000003	000023.948	-034.381
000004	000024.198	-034.389
000005	000024.446	-034.388
000006	000024.698	-034.388
000007	000024.945	-034.389
000008	000025.197	-034.383
000009	000025.445	-034.378
000010	000025.698	-034.381

Threshold measurement with delay and time expiration

This measurement example assumes that you have your sensor connected to a CW signal source. It also assumes that your source has an RF on/off button. Set up your source for:

- Frequency = 1 GHz
- Power = 0.0 dBm or 1 mW
- RF on/off = Off.

Key in the settings for the [Data Storage](#) tab and the [Measurement](#) tab.

Then select the [Meas Start](#) tab.

- Select the "...measured power exceeds threshold" radio button.
- Set the threshold to -10 dBm.
- Check 'Delay start of measurement'. Set the delay to 5000 ms.

Select the [Meas Stop](#) tab.

- Select the "...time expires" radio button. Set the time to 400 ms.

Get ready to observe the following:

- After clicking **Start**, no measurements are made (Status at the bottom of the window indicates that it is waiting for the threshold value).
- When you set the RF on/off button to On, there is a 5 s delay before measurements are made (Status at the bottom of the window indicates a pre-measurement delay).
- Then you see measurements made and the results displayed. You should see a brief message indicating the measurements are being made.

Examine the data and notice that the second column, last line indicates a time of about 400 ms. On a typical computer, there may be approximately 1500 measurements in that period.

Start and stop using time of day and measurement spacing

This measurement example assumes only that you have a sensor connected. Key in the settings for the [Data Storage](#) tab and the [Measurement](#) tab as required.

Then select the [Meas Start](#) tab.

- Select the "...time is equal to or later than" radio button. Set the start time for 10 minutes from now.
- Uncheck 'Delay start of measurement'.

Then select the [Meas Stop](#) tab.

- Select the "...time is equal to or later than" radio button. Set the stop time for 11 minutes from now.

Select the [Meas Spacing](#) tab.

- Select the 'Delay between points' radio button. Set the delay between points to 20 ms.

Get ready to observe the following:

- After clicking **Start**, no measurements are made until about 10 minutes have elapsed.
- The measurements then continue for about 1 minute.
- The measurements made, and the associated results, are displayed. There should be approximately 2900–3100 measurements (50 per second for 60 seconds). Each measurement is separated from the next by about 20 ms.

**CHINA Beijing**

Tel: [+86] (10) 6539 1166
Fax: [+86] (10) 6539 1778

CHINA Shanghai

Tel: [+86] 21 2028 3588
Fax: [+86] 21 2028 3558

CHINA Shenzhen

Tel: [+86] (755) 3301 9358
Fax: [+86] (755) 3301 9356

FRANCE

Tel: [+33] 1 60 79 96 00
Fax: [+33] 1 60 0177 69 22

GERMANY

Tel: [+49] 89 99641 0
Fax: [+49] 89 99641 160

INDIA

Tel: [+91] (0) 80 4115 4501
Fax: [+91] (0) 80 4115 4502

JAPAN

Tel: [+81] 3 3500 5591
Fax: [+81] 3 3500 5592

KOREA

Tel: [+82] (2) 3424 2719
Fax: [+82] (2) 3424 8620

SCANDINAVIA

Tel: [+45] 9614 0045
Fax: [+45] 9614 0047

SINGAPORE

Tel: [+65] 6873 0991
Fax: [+65] 6873 0992

TAIWAN

Tel: [+886] (2) 2698 8058
Fax: [+886] (2) 2698 8050

UK

Tel: [+44] (0) 1438 742200
Fax: [+44] (0) 1438 727601
Freephone: 0800 282388 (UK only)

USA

Tel: [+1] (316) 522 4981
Fax: [+1] (316) 522 1360
Toll Free: (800) 835 2352 (US only)

As we are always seeking to improve our products, the information in this document gives only a general indication of the product capacity, performance and suitability, none of which shall form part of any contract. We reserve the right to make design changes without notice. All trademarks are acknowledged. Parent company Aeroflex, Inc.

web: www.aeroflex.com

Email: info-test@aeroflex.com

April 2013